Land Registry Official copy of title plan


Title number NYK270539

Ordnance Survey map reference NZ9504NW

Scale 1:1250 enlarged from 1:2500

Administrative area North Yorkshire: Scarborough





This official copy issued on 22 April 2008 shows the state of this title plan on 22 April 2008 at 10:46:53. It is admissible in

evidence to the same extent as the original (s.67 Land Registration Act 2002). This title plan shows the general position, not the exact line, of the boundaries. It may be subject to distortions in scale.

Measurements scaled from this plan may not match measurements between the same points on the ground. See Land Registry Public Guide 19 - Title Plans and Boundaries.

This title is dealt with by Land Registry, Durham Office.





arid not NZ93264,04986

North York Moors National Park Authority The Old Vicarage Bondgate Helmsley York YO62 5BP

08/0861

Pt. 1

Telephone: 01439 770657 Email: dc@northyorkmoors-npa.gov.uk Website: www.moors.uk.net

Application for Planning Permission and listed building consent for alterations, extension or demolition of a listed building.

Town and Country Planning Act 1990

Planning (Listed Buildings and Conservation Areas Act) 1990

Publication of planning applications on council websites

Please note that with the exception of applicant contact details and Certificates of Ownership, the information provided on this application form and in supporting documents may be published on the council's website.

If you have provided any other information as part of your application which falls within the definition of personal data under the Data Protection Act which you do not wish to be published on the council's website, please contact the council's planning department.

Please complete using block capitals and black ink.

It is important that you read the accompanying guidance notes as incorrect completion will delay the processing of your application.

1. Applicant Name and Address	2. Agent Name and Address
Title: MR First name: COLIM	Title: First name:
Last name: DUK12	Last name:
Company (optional):	Company (optional):
Unit: House number: 9. House suffix:	Unit: House House
House name:	House name:
Address 1: ASHBURM CROFT	Address 1:
Address 2:	Address 2:
Address 3:	Address 3:
TOWN: WETHER 67	Town:
County: WEST YORKSHEE	
Country:	County:
Postcode: LS 22 SRE	Country:
	Postcode:
3. Description of Proposed Works	
Please describe details of the proposed development or works inc building(s):	cluding details of proposals to alter, extend or demolish the listed
•	NYMNPA
	2 4 NOV 2008
Is-at-	
or wor	please state the date when the development k(s) were started (DD/MM/YYYY):
ork(s) been completed? Yes No or work	nust be pre-application submission) please state the date when the development k(s) were completed (DD/MM/YYYY):
(date n	nust be pre-application submission)

10. Demolition	11. Listed Building Arterations
Does the proposal include the partial or total demolition of a listed building? Yes V No	Do the proposed works include alterations to a listed building? Yes No
If Yes, which of the following does the proposal involve?	If Yes, do the proposed works include: (you must answer each of the questions)
a) Total demolition of the listed building: b) Demolition of a building within	a) Works to the interior of the building? Yes No
the curtilage of the listed building: C) Demolition of a part of the listed building: Yes No	b) Works to the exterior of the building? Yes No
If the answer to c) is Yes:	c) Works to any structure or object fixed
i) What is the total volume of the listed building?(cubic metres)	to the property (or buildings within its curtilage internally or externally? Yes No
ii) What is the volume of the part to be demolished?(cubic metres)	d) Stripping out of any internal wall, ceiling
iii) What was the (approximate) date of the erection of the part to be removed? (MM/YYYY) (date must be pre-application submission)	or floor finishes (e.g. plaster, floorboards)? Yes No if the answer to any of these questions is Yes, please provide
Please provide a brief description of the building or part of the building you are proposing to demolish:	plans, drawings, photographs sufficient to identify the location, extent and character of the items to be removed, and the proposal for their replacement, including any new means of structural support and state references for the plan(s)/drawing(s):
	Structural support and state references for the plant(s)/drawing(s).
Why is it necessary to demoiish or extend (as applicable) all or part	
of the building(s) and or structure(s)?	
1 200 (4)	
12. Listed Building Grading	13. Immunity From Listing
Please state the grading (if known) of the building in the list of	Has a Certificate of Immunity from Listing been sought in respect of
Please state the grading (if known) of the building in the list of Buildings of Special Architectural or Historic Interest? (Note: only one box must be ticked)	
Please state the grading (if known) of the building in the list of Buildings of Special Architectural or Historic interest? (Note: only	Has a Certificate of Immunity from Listing been sought in respect of this building?
Please state the grading (if known) of the building in the list of Buildings of Special Architectural or Historic Interest? (Note: only one box must be ticked)	Has a Certificate of Immunity from Listing been sought in respect of this building? No Don't know
Please state the grading (if known) of the building in the list of Buildings of Special Architectural or Historic interest? (Note: only one box must be ticked) Grade I	Has a Certificate of Immunity from Listing been sought in respect of this building? No Don't know If Yes, please provide the result of the application:
Please state the grading (if known) of the building in the list of Buildings of Special Architectural or Historic Interest? (Note: only one box must be ticked) Grade I	Has a Certificate of Immunity from Listing been sought in respect of this building? Pes No Don't know If Yes, please provide the result of the application: NYMNPA
Please state the grading (if known) of the building in the list of Buildings of Special Architectural or Historic interest? (Note: only one box must be ticked) Grade I	Has a Certificate of Immunity from Listing been sought in respect of this building? Pes No Don't know If Yes, please provide the result of the application: NYMNPA
Please state the grading (if known) of the building in the list of Buildings of Special Architectural or Historic interest? (Note: only one box must be ticked) Grade I	Has a Certificate of Immunity from Listing been sought in respect of this building? Yes
Please state the grading (if known) of the building in the list of Buildings of Special Architectural or Historic interest? (Note: only one box must be ticked) Grade I	Has a Certificate of Immunity from Listing been sought in respect of this building? Yes No Don't know If Yes, please provide the result of the application: NYMNPA 2 4 NOV 2008 of on-site parking spaces: Total proposed (Including spaces retained) Difference In spaces.
Please state the grading (if known) of the building in the list of Buildings of Special Architectural or Historic interest? (Note: only one box must be ticked) Grade	Has a Certificate of Immunity from Listing been sought in respect of this building? Yes
Please state the grading (if known) of the building in the list of Buildings of Special Architectural or Historic interest? (Note: only one box must be ticked) Grade	Has a Certificate of Immunity from Listing been sought in respect of this building? Yes No Don't know If Yes, please provide the result of the application: NYMNPA 2 4 NOV 2008 of on-site parking spaces: Total proposed (Including spaces retained) Difference in spaces.
Please state the grading (if known) of the building in the list of Buildings of Special Architectural or Historic interest? (Note: only one box must be ticked) Grade I	Has a Certificate of Immunity from Listing been sought in respect of this building? Yes No Don't know If Yes, please provide the result of the application: NYMNPA 2 4 NOV 2008 of on-site parking spaces: Total proposed (Including spaces retained) Difference In spaces.
Please state the grading (if known) of the building in the list of Buildings of Special Architectural or Historic interest? (Note: only one box must be ticked) Grade I	Has a Certificate of Immunity from Listing been sought in respect of this building? Yes
Please state the grading (if known) of the building in the list of Buildings of Special Architectural or Historic interest? (Note: only one box must be ticked) Grade I	Has a Certificate of Immunity from Listing been sought in respect of this building? Yes
Please state the grading (if known) of the building in the list of Buildings of Special Architectural or Historic interest? (Note: only one box must be ticked) Grade I	Has a Certificate of Immunity from Listing been sought in respect of this building? Yes

	Existing (where applicable)	Proposed	Not applicable	Don Knov
External walls				
Roof covering	RED PANTILES.	INSULATE - ROOFING PE NEW FASCIA BOARD + SEE ATTACHED		
Chimney				
Windows			Ø	
External doors			1	
Celilngs			GZ∕	
nternal walls	LOUNGE/KITCHEN BATTENING + HARDBOARD	LOUNGE/KITCHERO DAC MEMBRANE BATTENING+PLASTERBOAK	₽ □	
loors				
nternal doors			図	
ainwater goods			M	
oundary treatments e.g. fences, walls)	education of the control of the cont	NYMNPA 2.4 NOV 2008	Ø	
ehide access and ard standing			Ø	
ghting	BELOW STANDARD EXISTING WIRING	REWIRING		
thers dd description)	FIREPLACE - 1960'S BRICK FIREPLACE, BROKEN FIRE CRAFE QUARK	BRICKUTORK, MULTIFUEL BRICKUTORK, MULTIFUEL STOVE, OAK BEAM.	NAC -	
e vou supplying addi	itional information on submitted drawings or plan			· ·

16. Foul Sawage	17. Assessment of Flood Risk
Please state how foul sewage is to be disposed of: Mains sewer Cess pit	is the site within an area at risk of flooding? (Refer to the Environment Agency's Flood Map showing flood zones 2 and 3 and consult Environment Agency standing advice and your local
Septic tank Other	planning authority requirements for information as necessary.)
Package treatment plant Unknown	If Yes, you will need to submit a Flood Risk Assessment to consider
Are you proposing to	the risk to the proposed site.
connect to the existing drainage system? Yes No	Is your proposal within 20 metres of a watercourse (e.g. river, stream or beck)? Yes No
if Yes, please include the details of the existing system on the application drawings and state references for the plan(s)/drawing(s):	watercourse (e.g. river, stream or beck)? Will the proposal increase the flood risk elsewhere? Yes No Unknown
	How will surface water be disposed of?
	Sustainable drainage system Existing watercourse
	Main sewer Unknown
18. Biodiversity and Geological Conservation	19. Existing Use
is there a reasonable likelihood of the following being affected	Please describe the current use of the site:
adversely or conserved and enhanced within the application site, or on land adjacent to or near the application site?	HOLIDAY RENTAL
a) Protected and priority species:	III TOUTONG RENGAL
Yes, on the development site	
Yes, on land adjacent to or near the proposed development	Is the site currently vacant?
No No	If Yes, please describe the last use of the site:
	NYMNPA
b) Designated sites, important habitats or other biodiversity features:	
	2 4 NOV 2008
Yes, on the development site	
Yes, on land adjacent to or near the proposed development	When did this use end (If known)? 20-9.08
No	(date where known may be approximate)
	Does the proposal involve any of the following:
c) Features of geological conservation importance:	Land which is known to be contaminated? Yes No
Yes, on the development site	suspected for all or part of the site? Yes No
Yes, on land adjacent to or near the proposed development	A proposed use that would be particularly vulnerable to the presence of contamination? Yes L-No
No No	If you have answered Yes to any of the above, you will need to submit an appropriate contamination assessment.
20 Mans and Modgas	
20. Trees and Hedges Are there trees or hedges on the	21. Trade Effluent Does the proposal involve the need to
proposed development site?	dispose of trade effluents or waste? Yes No
And/or: Are there trees or hedges on land adjacent to the proposed development site that could influence the	if Yes, please describe the nature, volume and means of disposal of trade effluents or waste
development or might be important as part Yes Yo	
if Yes to either or both of the above, you will need to provide a full	
Tree Survey, with accompanying plan before your application can be determined. Your Local Planning Authority should make clear	
on its website what the survey should contain, in accordance with the current 'BS5837: Trees in relation to construction -	<u>[</u>]
Recommendations'.	[

	Propo	sed	Hou	sing					Exi	stin	g Ho	using	•		
Market	Not	L	Nun	ber o	f Bedi	ooms	Total	Market	No	.	Nu	mber	of Bed	rooms	Tota
Housing	known	1	2	3	4+	Unknown	;	Housing	knov	•	1	2 3	4+	Unknowr	4
Houses	<u>. □.</u>	_	-		<u> </u>			Houses	[
Flats and maisonette	 -		ļ		1		·	Flats and maisonettes							
Live-work units	<u> </u>	<u> </u>	_	<u> </u>				Live-work units							
Cluster flats				ļ	<u> </u>			Cluster flats							
Sheltered housing	<u> </u>		<u> </u>	<u> </u>			_ · _	Sheltered housing						ļ	
Bedsit/studios	<u> </u>		$oldsymbol{oldsymbol{oldsymbol{eta}}}$					Bedsit/studios						<u>.</u>	
Unknown type								Unknown type						ļ	
· 	T	otali	(a+1	5+c+	d + e	+f+g)=				Tot	is (a	+ b + c	+ d + e	(+f+g)=	1
· · · · · · · · · · · · · · · · · · ·			•												
Social Rented	Not	1	Num 2	ber of		ooms Unknown	Total	Social Rented	Not know	_	,	mber o			Total
Houses			-	1 3	4+	UNKNOWN		Houses		+	1 2	3	4+	Unknown	
Flats and maisonette	 		ļ		200.70	. 35 20023		Flats and malsonettes		+-	37 15.	-		1114714	
Live-work units			-					Live-work units		╫			-	1	
Cluster flats								Cluster flats		+		 -	+		
Sheltered housing		· ·		 				Sheltered housing		+	+	+			
Bedsit/studios					ļ			Bedsit/studios		+	╅┈		- 		
Unknown type								Unknown type	一一	+			+	 	
7		otels	(a + t	+ + +	d+e	+f+g)=				Tota	ils (a -	b+c-	- d + e	+f+g)=	
			·		:										 •
Intermediate	1,,,		Number of Bedi			 	Total	Intermediate	Not	Ľ	_	nber o			Total
<u>. </u>	known	_1_	2	3	4+	Unknown		<u> </u>	know	<u> </u>	2	3	4+	Unknown	
Houses								Houses		+-		<u> </u>			
Flats and malsonettes			<u> </u>					Flats and maisonettes	<u> </u>	┿	-+		ļ. ————————————————————————————————————		
Live-work units							$-\parallel$	Live-work units		 		₩¥	NP	A	
Cluster flats	무							Cluster flats		- -	4,	A NO	1 200	0	
Sheltered housing			<u> </u>			·		Sheltered housing				4 NOV	200	0	<u> </u>
Bedsit/studios								Bedsit/studios	닠	┿	+	+-	ļ <u>-</u>		
Unknown type				لِللا				Unknown type	<u> </u>				 		-
	16	tals	(a + b	+C+	a+e-	+f+g)=				OU	15 (4 +	0+64	0+6	+f+g)=	
	Not		Numb	er of	Bedro	oms 1	Total		Not	Ť	Nur	nber of	Bedro	ooms	Total
Key worker	known	1	2	3		Unknown		Key worker	cnow	3 1	2	3		Unknown	
Houses					: .			Houses		_			<u> </u>		
Flats and maisonettes						<u> </u>		Flats and maisonettes				<u> </u>			
Live-work units								Live-work units		:		- L.A.			
Cluster flats								Cluster flats							
Sheltered housing					<u> </u>			Sheltered housing						·	·
Bedsit/studios								Bedsit/studios			<u> </u>	<u> </u>	<u> </u>		_
Unknown type					<u>.</u>			Unknown type							
-	To	tals	(a + b	+ C +	d+e-	+ f + g) =]			Tota	is (a +	b +c+	d+e	+f+g)=	
Total existing	resident	ial u	nits	(A+1	B+C-	+ D) =	- 71	Total proposed :	eside	ntia	l unit	(E -	F+G	+ H) =	

lfvo	u have answ	vered Yes to t	he au	estion above ple	ase add details	in the follow	ing tah	le:				
	Use class/type of use				Gross intern to be lost b use or de	al floorspace y change of molition metres)	Tot floor (incl	al gross interna rspace propose uding change ()(square metre:	d intern of following	Net additional gross internal floorspace following developmer (square metres)		
A1	S	hops										
• ,	Net trac	dable area:				· #=-						
A2	Finan professio	ncial and onal services										
А3	Restaurar	nts and cafes				·						
A4	Orinking e	stablishments				***************************************						
A5	Hot food	l takeaways								······································		
B1 (a)		her than A2)										
B1 (b)		rch and opment										
B1 (c)		ndustrial										
B2	 	industrial			V			W. HT W				
88		distribution										
C1		nd halls of dence				·			* (
C2		institutions						· · · · · · · · · · · · · · · · · · ·				
D1		sidential utions			·							
D2	Assembly	and leisure						NYI	MNPA			
THER	ER Please specify							24 N	OV 2008			
	-											
	То	tal		<u> </u>	·							
Jse -	Time of use	Not E	xistir	itutions and host ng rooms to be lo	st by change	Total rooms	propos	sed (including	1.5 Table 1	onal rooms		
lass '	Hotels	applicable		of use or demo	lition	cna	nges o	ruse)				
	Residential				· 					<u> </u>		
	nstitutions									······································		
ther	Hostels											
	noyment mplete the fo	ollowing infor	matic	on regarding emp	oloyees:	. ,		and the second s				
	· · · · · ·		F	ull-time	Part-	time		otal full-time equivalent	Not	known		
	Existing employees											
Рторо	osed employ	/ees				·						
	s, or Oper		g for	each non-resider	ntial use propo	sed:						
	Use Monday to Friday		(· ·	Saturday			day and Holidays	Not k	nown			
					·-····································		. '	· · · · · · · · · · · · · · · · · · ·	·			
		.			<u> </u>			<u> </u>		·		
						j			1			

Please state the site area in hectares (ha)

Tristrial or Commercial Proc	.05361	s and Machine	ry			
Please describe the activities and processe be carried out on the site and the end proc plant, ventilation or air conditioning. Pleas type of machinery which may be installed	ducts i	ncluding				e estimate de la constanta de
Is the proposal a waste management devel			☐ No			
If the answer is Yes, Please complete the fol	Not applicable		ity of the void in ering surcharge over or restoration	and making no	Please provide the r annual operational the the following waste	roughput of
Inert landfill	2 8		772300 01 710 03 11	inquie waste)		<u> </u>
Non-hazardous landfill	 					<u></u>
Hazardous landfill	片	<u>.</u>		<u> </u>	· · · · · · · · · · · · · · · · · · ·	
Energy from waste incineration	片	<u> </u>			<u></u>	
Other incineration	┟╬╁	-		1	 	
Landfill gas generation plant	片					
Pyrolysis/gasification	┟┼┤				·	<u> </u>
Metal recycling site	 					
Transfer stations	 		·			
Material recovery/recycling facilities (MRFs)	片			· · · ·	<u> </u>	<u> </u>
Household civic amenity sites	 	<u> </u>				
Open windrow composting	┝╬┼		· · · · · · · · · · · · · · · · · · ·		· · ·	
In-vessel composting	┝╬┼					·
Anaerobic digestion	井				<u> </u>	
	 				<u> </u>	<u>, </u>
Any combined mechanical, biological and/ or thermal treatment (MBT)	<u> </u>					
Sewage treatment works						
Other treatment Recycling facilities construction, demolition and excavation waste			- · · · · · · · · · · · · · · · · · · ·		···· 4. ···· ·· 7. ···	
Storage of waste	一	·				
Other waste management		<u></u>				<u> </u>
Other developments						
	<u> </u>				NVAMEA	
Please provide the maximum annual operation	onal th	roughput of the fo	ollowing waste :	streams:	NYMNPA	<u> </u>
Municipal					2 4 NOV 2008	
Construction, demolition and ex		on				
Commercial and Industri	al . <u></u> -	Astrophysical Charles (1997)	atat 200 a. katabas			AL DOE BY
Hazardous	4 T			an Maria Descrip		
if this is a landfill application you will need to planning authority should make clear what it	provid	de further informa ation it requires or	ition before you: I its website.	application can	be determined. Your wa	iste
 ∃azardous Substances 					, a , \$c.~;	-
Does the proposal involve the use or storage the following materials in the quantities state			No - 2 / Table	Not applicab		The second secon
fYes, please provide the amount of each sub	1017 p.350	Ang Pikhan <mark>Tana</mark> da ay kati Prates di S			다마고 있는 이 전에 전시기를 받아 있 100 기계를 보고 있는 이 이 100 kg (1)	
Acrylonitrile (tonnes)		nylene oxide (tonn	es)		Phosgene (tonnes)	
Ammonia (tonnes)	Hydro	gen cyanide (tonn	es)	Sulp	hur dioxide (tonnes)	
Bromine (tonnes)	Lic	quid oxygen (tonn	es)		Flour (tonnes)	
Chlorine (tonnes) Liq	uid pe	troleum gas (tonn	es)	Refined v	white sugar (tonnes)	
Other:			Other:			
imount (kilograms);			Amount (kilo	grams):		- REC. 10

. 32. Applicant Contact Details	33. Agent Contact Details
Telephone numbers Extension	Telephone numbers Extension Country code: National number: number:
Country code: National number: number:	Country code: National number: number: Country code: Mobile number (optional):
Country code: Mobile number (optional):	Country code: Fax number (optional):
Country code: Fax number (optional):	Email address (optional):
email address (optional):	Entail address (optional).
34. Site Visit	
Can the site be seen from a public road, public footpath, bridleway o	r other public land? Yes No
If the planning authority needs to make an appointment to carry out a site visit, whom should they contact? (Please select only one)	Agent Applicant Other (if different from the agent/applicant's details)
If Other has been selected, please provide: Contact name:	Telephone number:
Email address:	
	NYMNPA 2 4 MOV

24 NOV 2008

Design and Access Statement

For alterations to Brudenell Cottage, Chapel Street, Robin Hoods Bay.

Layout - To remain unchanged.

Scale - Existing sizes to remain.

Landscaping – To remain unchanged.

External Appearance -

Front elevation – addition of gas pipe, boiler vent and drain off pipe for central heating connection.

Rear of property – roof tiles and velux window to be replaced on rear extension due to severe leakage of rainwater into kitchen walls and units due to roof tiles badly aligned, causing rotten wood fascia as rainwater has been running down rear kitchen wall internally. The plan is to felt the roof space, replace velux window which has been broken and is unsafe with equivalent velux, replace rotten fascia board and re tile using pantiles from recommended list – Greenwood Natural red pantiles.

Access – There is only pedestrian access to the property. All building goods are to be stored inside the property or in front garden and removed at the end of each day.

There are no changes planned for the main roof structure, windows, door, eaves or curved kneelers.

NYMNPA

2 4 NOV 2008

Tony Easton & Son

98 Coach Rd Sleights Whithy YO22 5EQ

Electrical Installation Engineers

Tel Mob

Email tonyelec7 @ aol.co.uk Or visit our web site at www.tonyelec.co.uk

NICEIC Approved Contractor & Domestic Installer
FAO Mr E Astin

Ref: Brudunel Cottage Chapel St Robin Hoods Bay 02/05/2008 4022 45Q

Electrical report (Visual with earth loop test non NIC-EIC)

I have today visited the above property and given an electrical inspection. The findings are as follows.

The installation is dated about early to mid 1960s and is in need of an upgrade if not a rewire

The lighting is in the worst condition with a mixture of early PVC-VIR and lead cabling, some of which is not earthed. The only solution is to rewire the lighting.

There are a few sockets in the building most of which are wired on a radial circuit, most date back to the late 60s or mid 70s.

There is no main earth boding to the main services.

The fuse box is old and in need of replacing.

The building has storage heaters which are in a good condition although some of the wiring is loose and in need of a tidy.

To rewire the lighting, carry out main earth bonding and fit a new split phase circuit breaker board, I would place a PC sum of £2600.00. + VAT

To completely rewire a PC sum of £3500.00 + VAT.

NYMNPA 2 4 NOV 2008


NYM / 2008 / 0 8 6 1 / F L

A PC sum is an approximate costing depending on the customers needs, it is for a fully flush rewire with all plaster work made good. It could be less if the customer wanted surface wiring.

We will await your reply and will make a £70.00 + VAT charge for this survey in two weeks, refundable if we are given the work.

We are NIC-EIC approved contractors and registered for Part P.

If we can be of any further help please do not hesitate to contact us.



NYMNPA 2 4 NOV 2008 DIZMILS OF GND PIRE: BROUGHT IM AT GROUND FLOOR LENGT.

BLACK. - WIETH.

BOILING COMPENDING PIPE BROUGHT DOWN LM SIDE OF HOUSE AND TAKEN CUTAFTOUR CANEL PARITHO BLACK CUTAFTOUR CANEL PARITHO BLACK

WIMPOW FOR LIVE RIPLACEMENT BUT LIVE FOR LIVE RIPLACEMENT BUT MIZTRIC SIZE SEE BUCCOSIDO PICTOME.

> NYMNPA 0 5 DEC 2008

Brudnell Cottage Chapel Street YO22 4SQ

C3 DAMPNESS

The damp proof course is a waterproof barrier at low level in the walls to stop moisture from the surrounding ground rising up through the structure to cause problems with internal dampness.

It is possible due to the age type of property that it may have been constructed without any provision for a damp proof course, and there was no evidence of any subsequent damp proof course being installed.

Your Legal Adviser should make formal enquiries to establish whether any such works have been carried out, and if so, the extent of such works, and whether there is a valid transferable guarantee available in respect of such works.

Our tests for dampness were carried out with a standard moisture meter however they were severely restricted as the majority of the inner face to the external walls and internal walls have been either dry lined (i.e. the internal surface of the walls is formed on timber panelling fixed to the inner face of the masonry walls) or tiled.

Both of these types of finishes can mask problems with dampness therefore we can give no assurance that the areas behind are free from such problems. It would also be normal to expect some form of protection against dampness to have been incorporated within the construction of the dry lining to reduce but not fully exclude the risk of rot to the timbers abutting the damp walls.



It is likely that other areas not readily acessible, will also be affected, however in the absence of timber floors at ground level there is limited potential for significant decay of nearby timber, but the risk of spoilt decorations and perished plaster remains.

We also suspect the property is likely to suffer from problems with penetrating dampness due to the fact that it is built on a steeply sloping site therefore sections of the external walls to the rear elevations are built below ground level therefore will be suspect to dampness percolating through from the raised ground levels.



C4 CONDENSATION & INSULATION

There was no evidence of any significant problems with condensation at the time of our inspection, although as an older property it will be prone to such problems therefore it would be prudent to ensure there is adequate ventilation particularly to the kitchen and bathroom to reduce the risk of such problems developing.

Although a detailed Energy audit has not been carried out, the general standard of the thermal insulation properties of the property is consistent with others of a similar age and type which over-all will be reasonable bearing in mind its age. The attic room is likely to have poor levels of thermal insulation therefore is likely to be excessively hot or cold in summer and winter weather conditions respectively.

© THE ROYAL INSTITUTION OF CHARTERED SURVEYORS 2005

HOMEBUYER

during the Inspection if there is heavy rain.

THE SURVEY

Brudnell Cottage Chapel Street YO22 4SQ

PLEASE READ
THESE NOTES

C: THE BUILDING (continued)

The roofs, chimneys and other external surfaces of the building are examined from ground level, where necessary from adjoining public property and with the help of binoculars. The roof structure is examined from inside the roof space where accessible (insulation material, stored goods and other contents are not moved or lifted). The efficiency of rainwater fittings (gutters and downpipes) can only be assessed properly

C5 THE EXTERIOR

The roof slopes are evenly laid and have an adequate pitch for the type of roof covering used.

 Roof structure and covering

The stone ridge tiles are in serviceable order and evenly laid although the pointing is weathered with an isolated missing section therefore will require some basic maintenance in due course.

The terracotta pantile roof to the front elevation appears to be of some age and to be man made (rather than machine made), the shape of which can vary immensely, which increases the risk of wind damage. The overall condition of this section of the roof covering is reasonable, although there is some slight damage to individual tiles, whilst others are slightly displaced which increases the risk of further damage and leaks developing.

The roof covering the rear elevations appears to be formed with more recently machine made tiles which are more consistent in shape than those to the front, they are evenly laid and in serviceable order with no evidence of any significant defect nor disrepair.

The stone cappings to the shallow parapet wall above the left hand wall of the property are evenly laid and appear to be in serviceable order, but are weathered. We cannot confirm whether there is any provision for a damp proof membrane beneath these coping stones therefore unless maintained to a high standard there remains a risk that they may suffer from problems with penetrating dampness which could affect the walls beneath.

The lead flashings at the junction at the main body of the property and roof of the off shoot appear to be recent adequately formed and in serviceable order.

Chimneys

The chimney is of brick construction surmounted with two older terracotta pots which has cement flaunching to the junction between the base of the stack and surrounding roof covering.

The overall condition of the stack, pots and cement fillets is serviceable for its age. However there is evidence of some weathering to the brick and cement work which will require the due course.

2 4 NOV 2008

It would also be prudent to fit capped and vented cowlings to the disused chimney pots in order to reduce the risk of penetrating dampness developing.

The property has cast iron gutters set in metal brackets to the front elevation which discharge into the guttering of the adjoining property; Cranford cottage.

Your Legal Adviser should confirm details of the rights and responsibilities in respect of the shared rain water fittings.

The control of the second shows the second sho

Rainwater fittings

© THE ROYAL INSTITUTION OF CHARTERED SURVEYORS 2005 Brudnell Cottage Chapel Street YO22 4SQ



The plastic guttering and fall pipe to the rear elevation is of a standard quality and appears to be in serviceable order with no evidence of any significant defect nor disrepair.

Sections of the rainwater fittings appear to have shared drainage rights with the adjoining properties, your Legal Adviser should confirm details.

The walls are believed to be of solid or rubble filled cavity construction which would be typical for a Main wails property of this age and type.

> This type of wall is more likely to be prone to problems with damp penetration, consequently it is important to ensure that the external surfaces are maintained to a high standard to encourage rain water to run off the surface of the walls rather than penetrate any cracked or porous sections.

> The general condition of the stone work is satisfactory having regard to its age, with no evidence of any significant defect nor disrepair.

> The stonework at low level is weathered which is indicative of long standing problems with dampness and the probable use of a cement based mortar rather than a lime based mortar. The condition of the stone work will continue to deteriorate however, we do not feel that any immediate attention is required but would recommend that the cement based mortar should be replaced with a lime based mortar when the property is due for re-pointing.

> The property has single glazed windows set in timber sash frames some elements of which are believed to be recent replacements.

> The glazing and window frames appear to be in serviceable order having regard to their age and type; some weathering was noted to the older sections of the window frames and the decoration show signs of age therefore you should anticipate that these fittings will require over-haul in the short term.

> The double glazed Velux style sky light to the kitchen appears to suffer from problems with Internal condensation indicating that the seals to the unit have failed. Although this does not affect serviceability, visibility is reduced therefore you may wish to have this unit replaced as the only satisfactory solution is to replace the unit in its entirety.

> The entrance doors appear to be relatively modern part glazed units set in timber frames which appear to be of a suitable quality and in serviceable order having regard to their age and type.

> The external presentation of the property is satisfactory, however the paint work to the external timbers is showing signs of age therefore we anticipate your wish to have the property redecorated in the short term.

> There are no other external elements which require comment within the terms of this type of report.

External joinery

and decoration

Other

NYMNPA

24 NOV 2008

THE ROYAL INSTITUTION OF CHARTERED SURVEYORS 2005

HOMEBUYER THE SURVEY

Brudnell Cottage Chapel Street YO22 4SQ

PLEASE READ THESE NOTES

C: THE BUILDING (continued)

Floor surfaces and under-floor spaces are examined so far as they are accessible (furniture, floor coverings and other contents are not moved or lifted). If a part or area normally examined was found to be not accessible, this is reported; if a problem is suspected, advice is given on what action should be taken. It is not possible to assess the internal condition of any chimney, boiler or other flues. (In some cases, furnishings may conceal defects.)

C6 THE INTERIOR

> There is no roof space to the property due to the construction of the attic room; the cupboard to the rear of the attic room which holds the water storage tank does not have afford any more access as this area is also lined, under drawn with hard board sheeting.

Roof space

The ceilings are largely under drawn with some exposed floor joists and a section of exposed undersides of floor boards to the rear of the kitchen which is a typical cottage feature.

Ceilings

The overall condition of the ceilings and exposed floor joists is serviceable having regard to its age and type with no evidence of any significant defect nor disrepair.

Floors

Fitted floor coverings prohibited our inspection of the surface of the floors beneath therefore it would be prudent to inspect these as and when opportunities allow in order to access the true condition of these areas.

The ground floor appears to be of solid construction throughout where visible this appears to have a relatively modern concrete finish indicating it has been taken up and re-laid in recent times. There was no evidence of dampness to those small areas accessible indicating that they have probably been constructed with some form of damp proof membrane however this cannot be confirmed without extensive disruptive investigations.

The timber floors above are relatively firm but suffer some degree of distortion which is typical for a property of this age and type, which has suffered a minor degree of settlement. We cannot comment in detail upon the construction nor condition of the floor coverings due to the limitations of our inspection.

24 NOV 2008


Internal walls and partitions

Both the inner face of the external walls and the majority of the internal walls appear to be dry lined, as referred to in section C3 which appears to be of a basic quality and of some age. We cannot comment in further detail due to the limitations of our inspection although there remains the risk of hidden defects the extent of which cannot be confirmed from our limited inspection.

The internal wall between the bedroom and bathroom is of a light weight partition construction which appears to be in serviceable order but is likely to suffer from poor sound insulation qualities.

The property is fully decorated however, the finish to the surface of the dry lining/walls appears to be adequate bearing mind there type and overall quality.

Fireplaces etc.



We suspect the bedroom at first floor level would have also originally had an open fire place, but this has been sealed and boarded over. We cannot comment further due to the limitations of our inspectiom, but it would be prudent to provide some form of ventilation to the former flue to reduce the risk of a build up of moisture/condensation which can lead to problems with dampness developing.

© THE ROYAL INSTITUTION OF CHARTERED SURVEYORS

The chimney breasts appear to be complete though our inspection was limited due to lining etc.

HOMEBUYER THE SURVEY

Internal joinery and decoration **Brudnell Cottage Chapel Street YO22 4SQ**

The internal joinery is mainly of an older style with some recent replacement sections, the over-all quality is standard and its general condition satisfactory having regard to its age and type.

The staircase is of older timber construction whilst it appears to be firm there remains the risk, it may be affected by rot/decay to those areas not readily accessible.

The fitted units to the kitchen, are modern appear to be of a standard quality and in serviceable order. The appliances have not been tested as this falls outside of the scope of this type of report.

The internal presentation of the property is reasonable, the decorations are relatively modern and of an adequate quality, which appear to be in serviceable order.

There are no other internal elements which will require comment within the terms of this type of report.

Other

D: THE SERVICES & SITE

The efficiency, compliance with regulations and adequacy of design of services can only be assessed by tests conducted by suitably qualified specialists. Although surveyors are not specialists in these particular areas, an informed opinion can be given on the basis of the accessible evidence. Where possible, drainage inspection-chambers are examined (except in the case of flats), but drains are not tested during the Inspection. However, in all cases advice is given if there is cause to suspect a problem. Leisure facilities NYMNPA and non-permanent outbuildings are noted but not examined.

24 NOV 2008

PLEASE READ THESE NOTES

D1 THE SERVICES

Electricity

The property is connected to the mains electricity supply there are twin fuse bexes cupboard to the front reception room, one of which has been upgraded.

We are informed by the vendor that whilst gas is available in the locality, it is not connected to the subject property.

We are informed by the vendor that the property has mains water, the outside stop tap was not located the internal stop tap is in the kitchen.

Where visible the plumbing is in copper sections, which appears to be of a standard quality and in serviceable order. The waste pipes serving the sanitary fittings is, where visible formed in plastic sections which also appears to be of a standard quality and in serviceable order.

The header tank to the system is located in the built in cupboard to the rear of the attic room it is a modern plastic tank and appears to be in serviceable order although has not been fitted with a proper cover in accordance with current standards.

The hot water supply appears to be provided by electric immersion heaters situated in a modern firm lagged hot water cylinder which is located within the bathroom.

The system was not tested however the cylinder appears to be relatively modern with no evidence of any obvious defect nor disrepair.

© THE ROYAL INSTITUTION OF CHARTERED SURVEYORS 2005

The sanitary fittings to the bathroom are relatively modern and of a standard quality which appear to

■ Gas

Water