

# NYMNPA

## 18/11/2019



- Form new Utility/Store Room within the rear Yard. Existing walls to be left and the room is to be formed using an inner insulated and damp proofed skin.
- The new monopitched roof is to follow the line of a former outhouse evidence of which is provided by the remains of cement haunching on the stone wall.

- Kitchen Dining Room The solid floor has been removed due to serious defects-See Engineers Report. It appeared to have been a modern replacement built off substandard fill.
- It is intended to provide a new floor. Floating timber boards, vapour barrier onto Flooring grade insulation onto concrete floor
- Rear wall to be drylined with dpm behind lapped into floor dpm. System to be Newton Membrane allowing perculation on moisture, nothing applied to the wall.

D

- Lounge The timber floor has been removed leaving a large sub floor void. The structural problems are noted on the Engineers reports which form part of the application. Photographs will also be provided. The historic erosion has left areas where the original wall
- foundation stones are left exposed. New Floor; Inset from the existing walls provide a foundation slab cast to form a structural base. From this construct concrete block walls up to the underside of floor level, backfill between the new concrete walls and the lower levels of the house walls to provide support, include a newton membrane dpm as above to protect the building from damp but allow it to naturally percolate
- Structural elements must be to a structural engineers design.
- Span the void with a timber joist floor supported on the new concrete walls, infill between joists with insulation and line the top with timber floor boarding.
- Construction details to be provided, see 'schedule of works' and ensure Building Regulations are complied with

oposed


Do not scale from this drawing. only figured dimensions are to be taken from this drawing. The contractor must verify all dimensions on site before commencing any work or shop drawings. The contractor must report any discrepancies before commencing work. If this drawing exceeds the quantities taken in any way, the technician is to be informed before work is initiated. Work within the construction (design and management) regulations 2015 is not to start until a health & safety plan has been produced. This drawing is copyright and must not be reproduced without consent of BHD Partnership Ltd.

Contractor must not start without 'Pre Construction Information' from Principle Designer. If unsure contact BHD. Contractor must agree the 'Principle Contractor' roll with the client prior to commencement of the works. Ensure if required under CDM2015 regulations that the project is notified to the HSE.

## PLANNING ISSUE

## Initial Drawings for Client and Planning consideration only

Planning Schedule of Works to be provided



TIT TO POINT OF THE



Architecture + Engineering

Airy Hill Manor, Waterstead Lane, Whitby, N. Yorks. YO21 1QB.

Mr J Kingham

PROJECT:

CLIENT:

Refurb of Downhill Cottage New Road, Robin Hoods Bay

awing:	Existing and Proposed
	Elevations
	and Floor plans

DRAWING STATUS: Preliminary CHECKED: N I Duffield C Eynon SCALE @ SIZE: 1:50@ A1 11/11/19 DRAWING No

## D11726-02

Α