

AT

Dawn Paton

From: Planning
Sent: 22 May 2017 12:07
To: Planning
Subject: Comments on NYM/2017/0323/NM - Case Officer Mrs Ailsa Teasdale - Received from Building Conservation at The Old Vicarage, Bondgate, Helmsley, York, YO62 5BP,

Objection to two Velux windows to the eastern roof slope of the porch extension. This roofslope is highly visible from the street and the introduction of two Velux fixtures would detract from the traditional roofscape character, particularly due to the pantile roof material in which roof windows are especially prominent. I would suggest either locating a sun tube to the hidden western slope and piping it to the spaces required, or alternatively would permit one of the smallest available reproduction cast iron rooflights to the eastern slope - the CR6 from the Rooflight Company or equivalent size from other suppliers.

Please condition that the dry stone wall is constructed to match other examples in the immediate vicinity (appearance of stone and character of construction) and the masonry to the extension to the porch is constructed to match the existing building in coursing, appearance of stone and joint width. Lime mortar to be used.

Comments made by Building Conservation of The Old Vicarage Bondgate Helmsley York
YO62 5BP

Preferred Method of Contact is: Post

Comment Type is Object with comments
Letter ID: 478660

Comments are confidential.

