

Close up
of Daisy
Cotta



Daisy Cottage very much obscured by trees. Especially in summer.



similar aged property to Daisy
Cottage.
Opposite Church on
Church Lane.

Cheapest double
glazing - no dr. my
sashes or georgian
bars



Opposite Daisy Cottage,
Many different types of double glazing,
No Dummy sashes, no external georgian bars



A photograph of a white-painted wooden window frame. The frame consists of several horizontal and vertical slats. Handwritten measurements in black ink are present: a vertical double-headed arrow on the left side of the middle slat is labeled '12 mm'; a horizontal double-headed arrow on the right side of the middle slat is labeled '18 mm'; and a long horizontal double-headed arrow at the bottom of the frame is labeled '143 mm'. The wood grain is visible through the white paint. The background shows a window with multiple panes.

12 mm

18 mm

143 mm



45mm

← Ugly Weather Seal



Very Bad State of repair.
Lots of heat loss through
this door.