



1. North elevation of Rowan Barn. This building has been re-roofed and refurbished in the last few years.
2. North elevation of Rowan Barn.





3. East elevation of Mulberry Barn, an asbestos roof was fitted probably in the 1960's.
4. West elevation of Mulberry Barn with an asbestos roof and a pantiled lean-to.





5. Internal view at the junction between Mulberry Barn and Hornbeam Barn showing the existing king post trusses which are generally in sound condition although there is evidence of damp penetration.
6. General view across the courtyard to Hornbeam Barn and Mulberry Barn.





7. View of the eastern elevation of a section of Hornbeam Barn.
8. View of part of Hornbeam Barn with the north elevation of the southern range of courtyard buildings.





9. South elevation of Hornbeam Barn, a greenhouse has been removed in the past leaving a plinth wall.