0 6 FEB 2014




Photo 1 Roof slope to extension in June 2013 prior to works. Note damaged tiles.




Photo 2 Roof slope to extension in June 2013 prior to works. Note damaged tiles.




Photo 3 Roof slope to extension in June 2013 prior to works. Note damaged tiles.

0 6 FEB 2014




Photo 4 Roof slope to extension in June 2013 prior to works. Note damaged glass tiles.

MIMMANIDA




Photo 5 Roof after completion of works. Note same roof pitch and re-used tiles.



Photo 6 Roof after completion of works. Note conservation rooflight in position of glass tiles.

NYMN' 0.6 FEB_2014



Photo 7 Edge of roof after completion of works. Note picket fence to match existing yard fence.



Photo 8 Roof after completion of works.