

N O R T H W E S T

S O U T H E A S T

Natural slate roof to Porch


75mm diameter half round uPVC rainwater gutter. 50mm diameter uPVC fall pipe. Discharge to gravel.

Timber framed structure to form new Porch. Glazed panels using safety glass. Composite door with timber grain finish.

Where levels reduced: rebuild retaining boundary wall or construct independant stone structure to match existing.

N O R T H E A S T

Existing wrought iron gate to remain. New gate opening to be created in stone wall as shown. Timber gate posts to match existing & timber gate.



N O R T H E A S T E R L Y B O U N D A R Y

Proposed:

ALTERATIONS at 13 BARTONS ROW EGTON WHITBY

Drawing: PROPOSED ELEVATIONS.

Drawing No. 198/11 Date: JANUARY 2018 Scale: 1/50

MICHAEL MILLER BA(Hons) ARCH. CIAT Architectural Consultant.



16 PARK VIEW. GLAISDALE. WHITBY NORTH YORKSHIRE. YO21 2PP.

NYMNPA
16/02/2018