


NYMNP

28/07/2021



Mount Misery Roof Photos

Stable Roof



Purlin joint detail



General Decay



Lintel Decay

Wood Store



The picture shows the existing beam with the bird's mouth and existing wall plate



Vernacular alteration and general decay



General Decay
Tractor Shed



Roof timbers layout with wood worm infestation