

---

**From:** Craig Horrocks  
**Sent:** 01 April 2022 11:24  
**To:** Megan O'Mara  
**Subject:** Sandfield House Farm Alternative Door design.

Good morning Megan,

I hope you are well.

Following on from our conversation on Tuesday please see below the proposed changes to the doors D2 & D8 on the elevation drawing.

We would look at changing them both to D3 door design, the same as the others on the refurbishment.

I hope email is sufficient enough for your records, if it isn't then please let me know.

Thank you for your help and assistance on this matter

Kind regards  
Craig Horrocks  
Managing Director

Sandfield House Farm  
Sandsend Road  
Whitby  
North Yorkshire  
YO21 3SR

Section A-A Scale 1:50  
 Section B-B Scale 1:50  
 Section C-C Scale 1:50

First Floor Plan Scale 1:50  
 Ground Floor Plan Scale 1:50

Front Elevation Scale 1:100  
 Rear Elevation Scale 1:100

Notes:  
 1. All doors and windows to be replaced with UPVC composite doors and windows.  
 2. The existing floor structure is to be retained and repaired as necessary.  
 3. The existing roof structure is to be repaired as necessary.  
 4. The existing chimney stack is to be retained and repaired as necessary.  
 5. The existing brickwork is to be repaired as necessary.  
 6. The existing plasterwork is to be repaired as necessary.  
 7. The existing electrical wiring is to be repaired as necessary.  
 8. The existing gas supply is to be repaired as necessary.  
 9. The existing water supply is to be repaired as necessary.  
 10. The existing drainage is to be repaired as necessary.  
 11. The existing heating system is to be repaired as necessary.  
 12. The existing ventilation system is to be repaired as necessary.  
 13. The existing fire alarm system is to be repaired as necessary.  
 14. The existing fire escape system is to be repaired as necessary.  
 15. The existing fire extinguisher system is to be repaired as necessary.  
 16. The existing fire blanket system is to be repaired as necessary.  
 17. The existing fire alarm pull station system is to be repaired as necessary.  
 18. The existing fire alarm control panel system is to be repaired as necessary.  
 19. The existing fire alarm sounder system is to be repaired as necessary.  
 20. The existing fire alarm bell system is to be repaired as necessary.

Legend:  
 1. UPVC Composite Door  
 2. UPVC Composite Window  
 3. UPVC Composite Window  
 4. UPVC Composite Window  
 5. UPVC Composite Window  
 6. UPVC Composite Window  
 7. UPVC Composite Window  
 8. UPVC Composite Window  
 9. UPVC Composite Window  
 10. UPVC Composite Window  
 11. UPVC Composite Window  
 12. UPVC Composite Window  
 13. UPVC Composite Window  
 14. UPVC Composite Window  
 15. UPVC Composite Window  
 16. UPVC Composite Window  
 17. UPVC Composite Window  
 18. UPVC Composite Window  
 19. UPVC Composite Window  
 20. UPVC Composite Window

To be read in conjunction with Schedule of works.

Sandfield House Farm  
 Conversion to 2 No Holiday Cottages  
 Caravan park, Sandford Road  
 Proposed Building A  
 Floor Plans  
 Elevation & Sections  
 D11412-05

REPLACE D8 WITH D3 FULLY GLAZED

Side Elevation B Scale 1:50  
 Side Elevation D Scale 1:50

Replace D2 STABLE DOOR FOR D3 FULLY GLAZED.

Notes:  
 Scale set 1/10th in original below cell.