

From:
To: [Planning](#)
Subject: Re: NYM/2022/0666
Date: 19 October 2022 10:38:59

Good Morning

The Councillors discussed this planning application at their meeting on 28 September and have no objections.

Kind regards

Jude Wakefield
Parish Clerk and RFO
Fylingdales Parish Council

Please note, the clerk works variable part time hours but is normally available Monday and Wednesday.



Historic England

Mr A Muir
North York Moors National Park Authority
The Old Vicarage, Bondgate
Helmsley
YORK
YO62 5BP

Direct Dial: 0191 4031632

Our ref: **W**: L01544954

15 September 2022

Dear Mr Muir

Arrangements for Handling Heritage Applications Direction 2021

ST STEPHEN'S CHURCH, RAW PASTURE BANK, FYLINGDALES Application No. NYM/2022/0666

Thank you for your letter of 13 September 2022 regarding the above application for listed building consent.

Historic England provides advice when our engagement can add most value. In this case we are not offering advice. This should not be interpreted as comment on the merits of the application.

We suggest that you seek the views of your specialist conservation and archaeological advisers. You may also find it helpful to refer to our published advice at <https://historicengland.org.uk/advice/find/>

It is not necessary to consult us on this application again, unless there are material changes to the proposals. However, if you would like advice from us, please contact us to explain your request.

Yours sincerely

M Collins

Mike Collins
Team Leader (Development Advice)



37 TANNER ROW YORK YO1 6WP



From:
To: [Planning](#)
Subject: Comments on NYM/2022/0666 - Case Officer Mr A Muir - Received from Building Conservation at The Old Vicarage, Bondgate, Helmsley, York, YO62 5BP, via email: building@northyorkmoors.org.uk
Date: 23 September 2022 12:18:35

St Stephens Church, Raw Pasture Bank, Fylingdales

NYM/2022/0666

Listed Building consent for refurbishment/repair works to bell and re-installation in the cupola

Consultee response

Regarding the repair works to the bell and reinstating it at St Stephens Church, I have no concerns or issues. The bell seems to be native to the area and its return would allow its sound to be heard once more across the parish.

My concerns are linked to the structural soundness of the cupola itself. It seems that plans were approved in 2018/19 for repair works to the cupola and roof timbers below, with the inclusion of metal sections/splices. Within the supporting information attached to this application, within the DAS/HS (appendix) is a report from a Conservation Engineer (16/8/22). Within this report it is mentioned that the repairs are apparently “heavy handed”, “...in places don’t meet codified design practice” and, “The effects of timber decay to the truss and other secondary timbers do not appear to have been properly dealt with”. In addition, the report also notes that “Introducing the effects of the bell, given its modest size and weight, gut feeling says 'probably ok:, but because the support system is difficult to prove for support of the cupola itself, it’s the same for the bell. The additional effects of the bell are quite modest though, and if it's a bell that's hit with a hammer, then even smaller still”. I ask that the owner/applicant ensures that the cupola is structurally sound and more than capable of not only supporting this historical bell, but also being able to withstand the forces of the bell being rung endless amounts of times over many years; I would not want to see a historic bell destroyed because of inadequate support. Does the owner/applicant have any images of the completed cupola works for review and/or have any information to resolve this concern?

Comments made by Building Conservation of The Old Vicarage
Bondgate
Helmsley
York
YO62 5BP

Comment Type is Comment
Letter ID: 594825