







NORTH WESTELEVATION

SOUTH WEST ELEVATION














SECTION





the original glass company. Heritage thin sealed unit 3mm low e/4mm krypton/3mm outer pane.U = $1.9W/m^2K$



INSIDE

Unequal angle at head to support masonry.

Install black dense polythene dpc between steel \$ masonry. Continue wall lining at window head.

Seal frame to stonework externally Compriband tape \$ point externally sand/lime mortar.

Insulated plasterboard at window head with skim coat finish.

Window frame:

115 x 75mm head.

22 x 16 bead internally.

50 x 45 top rail of sash.

Glazıng:

The Original Glass Company Heritage double glazed units or equivalent. Comprising 3mm machine drawn glass/4mm krypton filled cavity/3mm coated Low-E inner pane. Units fixed with sprigs \$ linseed oil putty.

Glazing bar 44 x 27.

75 x 45 bottom rail of sash.

22 x 16 mm bead (surround internally).

22 x 10mm oak runner bead set in rebate in sill.

115 x 75mm oak sill.

ex. 25mm window bottom board.

Proposed:


ALTERATIONS to SHIRLEY HOUSE SUNNY PLACE ROBIN HOOD'S BAY

Drawing: ELEVATIONS II as PROPOSED


Drawing No. 190/13 Date: SEPTEMBER 2017 Scale: 1/50

MICHAEL MILLER BA(Hons) ARCH. CIAT Architectural Consultant.






PRINT TO A3



GROUND FLOOR



BASEMENT

Proposed:


ALTERATIONS to SHIRLEY HOUSE SUNNY PLACE ROBIN HOOD'S BAY

Drawing: EXISTING PLANS I


Drawing No. 190/01 Date: SEPTEMBER 2017 Scale: 1/50

MICHAEL MILLER BA(Hons) ARCH. CIAT Architectural Consultant.





ATTIC



FIRST FLOOR

Proposed:


ALTERATIONS to SHIRLEY HOUSE SUNNY PLACE ROBIN HOOD'S BAY

Drawing: EXISTING PLANS II

Drawing No. 190/02 Date: SEPTEMBER 2017 Scale: 1/50

MICHAEL MILLER BA(Hons) ARCH. CIAT Architectural Consultant.





Elec

meters

Damp proofing treatment to basement.

Excavate \$\psi\$ remove extg concrete floor slab. Excavate to formation levels \$\psi\$ if foundation levels permit: I 50mm hardcore/50mms and blinding / I 500g polythene dpm/ I 00mm concrete floor slab with Sovereign Aquaduct to perimeter of floor \$\psi\$ sunk into slab c/w jetting eye. Sovereign CDM 20 floor membrane/ 50mm Recticel floor insulation board/63mm screed with light A I 92 mesh reinforcement. Adjust spec to suit existing foundation levels eg. omit hardcore \$\psi\$ add well rammed earth.

NB. All Sovereign installations to be in accordance with manufacturers detailed drawings.

Extg brick lining wall removed from basement \$ prepare walls to receive Sovereign CDM8 damp proofing membrane tape sealed to floor membrane.

All Soverign products \sharp installation to be as manufacturers recommendations and installation instructions. Fix 50mm x 50mm treated sw battens \sharp 50mm ROCKWOOL rigid slab insulation. Vapour barrier. I 2mm MR plasterboard \sharp plaster skim coat.

Fix 19 x 150mm agee moulding timber skirting boards with proprietary fixitive (eq. Soudal Fixall).

New partition walls to be constructed as detail drawing 190.15 Four panel door to stairwell to be $\frac{1}{2}$ hour fire resisting with intumescent strips.

Existing inspection chamber to be fitted with double seal recessed cast iron frame \$ bolt down lid. Recess to be fitted with timber boards permanently secured. Ensure building owner is aware of the necessity to clear the silt bucket at regular intervals.

Existing timber staircase: string rotted where against wall. Carefully remove staircase to enable floor to be overhauled and staircase parts renewed as required. Re-fit staircase on completion of floor works. Treated timber frame support structure to staircase faced with 'V' jointed timber boards Class I surface spread of flame finished intumescent paint base coat/coats and flame paint top coat/coats, as manuf specification.

Ceiling. Existing insulation boards to be removed from ceiling. New installation as shown on 195.15 detail drawing. This is considered to be an improvement which increases the fire performance of the basement. The ceiling soffit assumes a greater fire resistance as the material is non combustiable, it has been tested and achieved Euroclass A1/BS. 476 Part 4. As a building with a basement this alteration is considered to be imperitive to the continued and future use of the building with regard to the safety of the occupants.

Joists to be coated intumescent paint base coat/coats and flame paint top coat/coats, as manuf specification.

Proposed:

ALTERATIONS to SHIRLEY HOUSE SUNNY PLACE ROBIN HOOD'S BAY

Drawing: PLANS I as PROPOSED

Drawing No. 190/10
Date: SEPTEMBER 2017
Scale: 1/50

MICHAEL MILLER BA(Hons) ARCH. CIAT Architectural Consultant.



Chartered Institute of Architectural Technologist Registered Practice

16 PARK VIEW. GLAISDALE. WHITBY NORTH YORKSHIRE. YO21 2PP.

BASEMENT

All areas: repair worm attected

floor boards with fillets.

Board or repair to span min

Repair defective purlin at bearing.


Existing lime plaster finish to be repaired or reinstated as site conditions dictate

Form new Shower Room: 50 x 75mm stoothing Rockwool Sound insulation between timbers. Vapour barrier to Shower Room side \$ finish 210mm t&g 'V' boards both sides. Finish with fire paint to provide Class O according to Building Regulation standards. 762mm 4 panel door to match existing elsewhere on pocket door track. Sanitary appliances connected as shown.

Shower cubicle: I 2.5mm plywood wall face wetwall boards over. Waterproof floor tanking system such as manufactured by WEDI.

Where walls required to be tiled install proprietary tile backer board. Heritage: this is reversible and since it would be plugged \$ screwed to the structure, it would not cause immense harm.





Remove lath \$ plaster ceiling.

Existing construction appears to be: Tiles on battens on lath \$ plaster torching.

For the purposes of this project it is considered that the lath \$ plaster torching is a breathable construction and will act much in the same way as a breathable membrane. It must be borne in mind that until the torching can be confirmed to be in complete repair, some water ingress may be expected. Improvement:

Fit 50mm Rockwool thermal insulation between rafters allowing 25mm air space between plaster/lath torching.

Fix 20mm wood fibre boards (approx 160kg/m³) to underside fof rafters \$ 10mm Lime Green Solo lime plaster coat.

Extg s/vp with new connection from shower.

GENERALLY:


Treat all existing timbers against insect and fungal attack using proprietary contractor.

Where existing floor boards are perished fit fillets to repair. Where larger sections are to be removed, replace board to span min of 3no joists.

New partition wall constructed 50 x 75mm stoothing. Rockwool sound insulation batts between timbers.

Existing skirting boards replaced with 19mm thick Georgian section.

Existing dry lining to first floor walls to be overhauled. Remove any rotted timbers. Add moisture resistant insulation. Vapour barrier. Plasterboard \$ skim coat as existing.



Existing bathroom tiling to be removed. Adjust/renew tile backer board to 1.35m above floor level \$ tile finish as Client directs.

Existing stonework above finished lime plaster. Water based emulsion finish.

New partition to Bathroom/Lobby constructed 50 x 75mm stoothing with Rockwool Sound insulation between timbers. Vapour barrier to bathroom side \$ finish 2 | Omm t\$g 'V' boards both sides. Finish with fire paint to provide Class O according to Building Regulation standards. 762mm 4 panel door to match existing.

Connect sanitary appliances to extq s/vp.

All areas: repair worm attected floor boards with fillets. Board or repair to span min 3no joists.

Extg rwp

Proposed:

ALTERATIONS to SHIRLEY HOUSE SUNNY PLACE ROBIN HOOD'S BAY

Drawing: PLANS II as PROPOSED


Drawing No. 190/11 Date: SEPTEMBER 2017 Scale: 1/50


MICHAEL MILLER BA(Hons) ARCH. CIAT Architectural Consultant.



16 PARK VIEW. GLAISDALE. WHITBY NORTH YORKSHIRE. YO21 2PP.

new svp in duct





SECTION thro' BASEMENT FLOOR


SHIRLEY HOUSE SUNNY PLACE ROBIN HOOD'S BAY

Drawing: BASEMENT FLOOR & WALL DETAILS


Drawing No. 190/15 Date: SEPTEMBER 2017 Scale: 1/5

MICHAEL MILLER BA(Hons) ARCH. CIAT Architectural Consultant.






SECTION



ELEVA



Proposed:

ALTERATIONS to SHIRLEY HOUSE SUNNY PLACE ROBIN HOOD'S BAY

Drawing: BASEMENT STRUCTURE SUPPORT POST to FFL.


Drawing No. 190/16
Date: SEPTEMBER 2017
Scale: 1/5

MICHAEL MILLER BA(Hons) ARCH. CIAT Architectural Consultant.



16 PARK VIEW. GLAISDALE. WHITBY NORTH YORKSHIRE. YO21 2PP.

PLAN



Floor joists with timber bearer 70 x 50mm fixed between @ 400mm centres in ceiling void.


Head of partition fixed to sw bearers between joists.

SW t&g timber boards wide faced approx 200mm approx 200mm

70mm sw studs & insulation.

Tomm Rockwool in floor void. Quietstone ceiling panel fixed to battens fixed to joists. See detail drawing 190.15

DETAIL ADJACENT DOOR



Proposed:


ALTERATIONS to SHIRLEY HOUSE SUNNY PLACE ROBIN HOOD'S BAY

Drawing: FIRST FLOOR PARTITION.

Drawing No. 190/17 Date: SEPTEMBER 2017 Scale: 1/5

MICHAEL MILLER BA(Hons) ARCH. CIAT Architectural Consultant.





FIRST FLOOR BEAM DETAIL

SECOND FLOOR BEAM DETAIL



FIRST & SECOND FLOOR BEAM INSTALLATION.

Drawing No. 190/18 Date: SEPTEMBER 2017

Drawing:

Scale: 1/5

