NYM / 2012 / n 2 8 5 / F L 1 3

INSPECTION OF BARNS AT BANNIAL FLATTS FARM, WHITBY

FOR

MR. P. SWALES AND MISS J. LONSDALE

NYMNPA -6 JUN 2012

BY R. O. BIRDSALL M.Sc., M.I.C.E. CHARTERED ENGINEER

+ 1000

imaginative architecture + engineering design

bhd partnership

Address:

Airy Hill Manor,

Whitby,

North Yorkshire, YQ21 1QB

1.0 INTRODUCTION

- 1.1 We confirm that we made an inspection of the barns (indicated on BHD drawing D10152-06A) at Bannial Flatts Farm, Whitby on 28th May 2012.
- 1.2 The purpose of the inspection was to determine the structural suitability of the barns for conversion to dwellings.


2.0 OBSERVATIONS

- 2.1 The walls all consist of coursed sandstone approximately 430mm thick.
- 2.2 The south west facing wall is in good condition, see photograph 1.
- 2.3 The north west facing wall is in good condition, see photograph 2.
- 2.4 The east facing walls are in good condition, see photograph 3.
- 2.5 The north east facing wall is in good condition, see photograph 4.


3.0 CONCLUSIONS

3.1 The barns are in very good structural condition and are suitable for conversion to dwellings provided the work is done in accordance with current Building Regulations.





PHOTOGRAPH 1 BANNIAL FLATTS FARM, WHITBY



PHOTOGRAPH 2 BANNIAL FLATTS FARM, WHITBY

29th May 2012 10152



PHOTOGRAPH 3 BANNIAL FLATTS FARM, WHITBY



PHOTOGRAPH 4 BANNIAL FLATTS FARM, WHITBY