**From:** Stephen Ballinger **Sent:** 25 January 2021 07:36

**To:** 'Helen Webster' **Cc:** 'Paul Barker'

Subject: RE: ADDITIONAL INFO TO ACTION - NYM/2020/0945/LB & /0944/FL

Dear Miss Webster
Thank you for your email

I am attaching amended drawings showing the removal of the proposed dormer window to the north elevation, and its replacement with a conservation rooflight:

2801.01A Second Floor Plans

2801.02A Roof Plans

2801.03A South-North Sections

2801.04A North Front Elevations

The originally submitted drawing no 2801.05, of the existing and proposed South Rear Elevations, remains unchanged.

The drawings show the *CR07-2 Between the Rafter* roof window manufactured by The Conservation Rooflight Company:

https://www.therooflightcompany.co.uk/all-products/conservation/


The structural dimensions are 583mm width x 882mm length. The top-hinged window would be framed out within the rafter line and neatly between the existing retained upper and lower purlins. The standard frame is of 3mm mild steel, with a polyester powder coating and black painted finish. The manufacturer does suggest the possibility of using an alternative stainless steel, or steel treated with a hot Zinc spray coating, for any application within a coastal property.


It is hoped that the foregoing will be acceptable. Should you require any further information of, or assistance with, the proposals prior to your determining the two applications, then please do not hesitate to contact me.

Many thanks again

Yours sincerely

Stephen Ballinger






2801.01<sup>A</sup> SECOND FLOOR PLANS


A monday 25 tonuary 2021.


Proposed domer window to north side of not removed. New conservation rooflight added.



2801.04<sup>A</sup> NORTH FRONT ELEVATIONS

A Monday 25 January 2021.
Proposed downer window removed.
New conservation rooflight added.







2801.02<sup>A</sup> ROOF PLANS

A monday 25 January 2021.

proposed domer mindow to north side of noof removed. New conservation rooflight added.





2801.03<sup>A</sup> SOUTH-NORTH SECTIONS

A monday 25 January 2021.

Proposed dormer window to north side
of roof removed. New conservation
rooflight added.