From: Neil Duffield
Sent: 15 February 2021 17:40
To: Helen Webster
Subject: NYM/2020/1006/FL & 1009/LB - Ingleby House E11947-25 NYMNPA revised window detail 15.02.21

Hi Helen,

Sorry for the late reply, and yes we would be happy to agree to an extension of time.

I attach revised drawings D11947-02F and 03B. Along with photo's of the existing interior. As you can see it has had a relatively modern refurbishment. Our clients are keen to look at salvaging items should they be discovered behind the studwork.


On the drawing the window is now set 125mm in reveal. Also we have had to amend the intermediate pilaster as our clients have discovered that the masonry pillar is an integral part of the original structural support.

Should you have any queries on the above just let me know. Kind regards Neil




The information contained in this email is intended only for the person or entity to whom it is addressed and may contain confidential and/or privileged material. If you have received this email in error please note that any review, retransmission, copying, dissemination or other use of, or taking of any action in reliance upon its contents is prohibited. If you are not an intended recipient please delete the material from any computer that may have it and contact BHD Partnership IT Personnel on 01947 829317, thank you for your co-operation.

The contents of an attachment to this email may contain software viruses which could damage your computer system. We cannot accept liability for any damage which you sustain as a result of software viruses, you should carry out your own virus checks before opening any attachment.








— See drawing D11947-03 for details


Internally;

interior with WC.

Retain exiting beams and leave exposed, paint may need to be fire resisting to these items Provide suspended ceiling between existing drop down beams (Beams remain visible). Ceiling to the timber framed with acoustic insulation and lined below with plasterboard and skim.

Following removal of existing modern refurbishment materials create the open plan Retail





window plan Scale 1:20

Do not scale from this drawing. only figured dimensions are to be taken from this drawing. The contractor must verify all dimensions on site before commencing any work or shop drawings. The contractor must report any discrepancies before commencing work. If this drawing exceeds the quantities taken in any way, the technician is to be informed before work is initiated. Work within the construction (design and management) regulations 2015 is not to start until a health & safety plan has been produced. This drawing is copyright and must not be reproduced without consent of BHD Partnership Ltd.

Contractor must not start without 'Pre Construction Information' from Principle Designer. If unsure contact BHD. Contractor must agree the 'Principle Contractor' roll with the client prior to commencement of the works. Ensure if required under CDM2015 regulations that the project is notified to the HSE.

## NYMNPA

## 16/02/2021

Drawing for initial planning and client consideration only				
B A	15/02/21 14/12/20	CE nid		o show ex post. for approval
REV	DATE	BY	A	MENDMENT
Architecture + Engineering Airy Hill Manor, Waterstead Lane, Whitby, N. Yorks. YO21 1QB. P: +441947 604871 F: +441947 600010 E: general@bhdpartnership.com				
Messrs R & G Hodgson				
PROJECT: Ingleby House King Street Robin Hoods Bay YO22 4SH				
Drawing: Proposed Detail Sheet				
DRAWING STATUS: Preliminary				
DRAWN: CHECKED: NID				
SCALE @ SIZE: DATE: shown @ A1 14/12/20				
DRAWING NO: D11947-03 REV: B				





## 16/02/2021



