

Andy Brown



1 message

David Morris < _____.
To: Andy Brown

Tue, Aug 15, 2023 at 1:30 PM

Afternoon Andy

Thank you for the photos that looks fine.

I know we checked all the escape windows when I originally visited, I thought the current hallway was remaining in 1A so the escape was going to be no worse for bedroom 5 than the existing layout. If the hallway wall is being removed and the staircase will come down into the lounge then yes bedroom 5 should have an escape window with a minimum opening of 450mm x 450mm x 0.33m² and max 1.1m internal floor to sill height.

An alternative would be to provide a link door between the two bedrooms so occupants can use bedroom 4 window without going out onto the landing or alternatively have an FD30 fire door on the landing so it forms a small lobby outside bedrooms 4 and 5 separating them for the ground floor.

Hope this makes sense but any questions just get back to me.

Regards

David Morris. BSc (Hons), MRICS

Building Control Surveyor



Delivering Local Authority Building Control Services in the former District and Boroughs of Hambleton, Richmondshire, Ryedale, Scarborough and Selby

Address: Suite 2 Coxwold House, Easingwold Business Park, Easingwold, YORK, YO61 3FB

