NYMNPA 21/09/2018

From: Office Sent: 21 September 2018 12:40 To: 'Hilary Saunders' Cc:

Subject: RE: Thirley Cotes NYM/2018/0499/LB

Dear Hilary

Thank you for your email of the 13<sup>th</sup> September, apologies for the slow response we have just moved our studio and are replacing all our IT systems. I would advise as follows to your points.

1. Concerning the greenhouse I would request a 'before construction of the greenhouse' condition to allow a manufacturer to provide full details for approval taking in the points you raised.

- 2. Concerning roof windows I would propose 'the conservation range' from the Roof Light Company with CR10 / 517mm x 980mm to all the roof lights except over the kitchen to Rowan and Mulberry to be CR14's / 821mm x 1133mm. I have revised the drawings and moved a couple to reduce regularity.
- 3. On Hornbeam I have shown the owl box removed as this will not be needed once the owl loft above is in use. I have also reduced the size of the window it does need to be suitable for means of escape.
- 4. Concerning flues I have put a general note on the drawings advising that they are to be kept as low as possible.

Hopefully this will now allow the application to be approved. Many thanks for your assistance with this development.

Regards

David

(drawings to follow)

From: Hilary Saunders Sent: 13 September 2018 10:02 To: Cc: Maria Calderon

Subject: FW: Thirley Cotes NYM/2018/0499/LB

NYMNPA 21/09/2018

Dear David,

Thankyou for the receipt of amended plans.

Both Maria Calderon (Building Conservation Officer) and I have now had the opportunity to consider the revised plans and overall, are happy with the revised plans, subject to the following minor alterations and additional information:

**Greenhouse** –Whilst similar style to the Old Rectory at Pickering would be suitable, historic details and style should be incorporated – these details can either be submitted now or be subject to a condition. This should include details such as the frame and any roof structure being very lightweight; if any of the side windows open, they should be top hung and discrete; appropriate window and door furniture. Also to note is that timber was not favoured in historic greenhouses due to the rate of decay. Where timber was used thinner sections were used as they absorbed less moisture and therefore were more resistant to decay. Double glazing would not be supported - the national park do not permit double glazing in historic buildings to regular windows and doors; as there is no precedence for this. Double glazing would also not be in keeping with the greenhouse and the lightweight approach that it should take. I would also require the be utilised.

**Veluxes** - we do not permit the instillation of Velux Conservation Rooflights. I have attached a list of suppliers of conservation rooflights that we feel are more appropriate. However, the size of P10 appears to be quite intrusive and should be reduced in size. Also their placement should be altered so that they appear less regular.

**Hornbeam** - The south gable appears a little cluttered. Please could the proposed window be omitted or at least reduced in size and an alternate suitable location be

found for the owl box (subject to environmental concerns).

**Flues** - The flues to the wood burners appear quite high; can these be reduced in height if this is compatible with building regulations.

**Hot tub area** - The area surrounding the hot tub to hornbeam has altered; the earlier arrangement, ie not on a raised platform is more appropriate.

**Repointing** - There is no mention or repointing in the application. If this work is to be undertaken it can be done under permitted development in a like for like manner. In the case of Thirley Cotes this would have historically been pointed with a quick lime mortar mix (not cement or NHL). Any deviation from this would require consent.

**Internal floors** - There is no reference to the treatment of internal floor surfaces. Please can this be clarified.

I am working through the files today in order to have the delegated report written with a recommendation for approval, subject to the above. I look forward to receipt of these amendments/clarifications at your earliest convenience.


Kind regards

Hilary


Mrs Hilary Saunders MRTPI Planning Team Leader Development Management

North York Moors National Park Authority The Old Vicarage Bondgate Helmsley York YO62 5BP

Tel. no. 01439 772700 Web: <u>www.northyorkmoors.org.uk</u> NYMNPA 21/09/2018








Harwood Dale, Scarborough

5/10/18 29/8/18



Section B / B - Hornbeam


Section A / A - Hornbeam




scale 1 / 50 at A1



THE OLD GRAMMAR SCHOOL MANOR SQUARE OTLEY LEEDS LS21 3AY RIDGE HALL RIDGE LANE STAITHES NORTH YORKSHIRE TS13 5DX





	NYMNPA 21/09/2018
	AMENDED
existing owl box to be retained / made good	
	existing 2.1m stone garden wall 90.00
made	close boarded timber door to provide access to amenity paddock. new opening with matching stone lintol

Harwood Dale, Scarborough P & G Durbin Properties

5/10/18 29/8/18

THE OLD GRAMMAR SCHOOL MANOR SQUARE OTLEY LEEDS LS21 3AY RIDGE HALL RIDGE LANE STAITHES NORTH YORKSHIRE TS13 5DX