

Amendments/Additional Information

- Amended layout of buildings/outside areas
- Additional background information
- Amended design
- Revised access arrangements
- Change of description of proposed development
- Change in site boundaries
- Other (as specified below)

HS.


Wendy Strangeway

From: Hilary Saunders
Sent: 04 January 2017 14:21
To: Planning
Subject: FW: NYM/2016/0818/FL Fusco
Attachments: D11039-06A.pdf


H. Saunders

Mrs Hilary Saunders
Planning Team Leader
Development Management

North York Moors National Park Authority
The Old Vicarage
Bondgate
Helmsley
York
YO62 5BP



Tel. no. 01439 772700
Web: www.northyorkmoors.org.uk



From: Tim Harrison (BHD)
Sent: 04 January 2017 13:37
To: Hilary Saunders
Subject: FW: NYM/2016/0818/FL Fusco

Good afternoon Hilary,

Happy New Year to you and all of your team, I hope you had a good time over the Christmas break.

With regard to the matter of lighting referred to in your e-mail we have prepared a plan to indicate the proposals which is attached for your consideration .

This shows bollard lighting to the car park area and jet wash bay along with integral led lighting panels below the canopy to provide lighting to the loading bay, and led lighting with sensors fixed to the building above the two staff entrances .

We have removed the idea of lighting on poles as you have noted these as being problematic and hopefully these proposals will be considered to be more sympathetic and in line with policy.

Please let me know your thoughts.

Many thanks for your assistance.

kind regards,
Tim

From: Hilary Saunders [<mailto:h.saunders@northyorkmoors.org.uk>]
Sent: 04 January 2017 10:29
To: Tim Harrison (BHD)
Subject: NYM/2016/0818/FL Fusco

Morning Tim

I've just been looking through the forms and plans for this one and I just have one queries which is that on the forms it states that external lighting will be installed on 5m poles – but I can't see the location of these on the plans.

Light pollution is a particular concern on the business park so I would be grateful for details of the location of lighting and details of light spread. It may be necessary to consider bollard lighting rather than lighting on high poles.

Thanks in anticipation.

Hilary

H. Saunders

**Mrs Hilary Saunders
Planning Team Leader
Development Management**

North York Moors National Park Authority
The Old Vicarage
Bondgate
Helmsley
York
YO62 5BP

Tel. no. 01439 772700

Web: www.northyorkmoors.org.uk

CONFIDENTIALITY: The contents of this message are the views of the author, not necessarily the views of the North York Moors National Park Authority. This is a private message intended for the named addressee(s) only. Its contents may be confidential.

If you have received this message in error please reply to say so and then delete the message. Any use, copying, disclosure or distribution by anyone other than the addressee is forbidden.

www.northyorkmoors.org.uk

This email has been scanned for email related threats and delivered safely by Mimecast.
For more information please visit <http://www.mimecast.com>
