

NYMNP  
12/07/2019



### Analysis Report

Report Number: J028604

Issue Date: 19/12/2018

Private & Confidential:  
A1 ENVIRONMENTAL  
A1 ENVIRONMENTAL  
4 THE PADDOCK  
CATTERICK VILLAGE  
RICHMOND  
NORTH YORKSHIRE  
DL10 7RZ

Premises of Sample Origin:  
1 MIDDLEWOOD LANE  
FYLINGTHORPE  
WHITBY  
YO2 4UB

Analyst: Amie Sowerby

Sampled by: A1 ENVIRONMENTAL

Date of Sample Receipt: 18/12/2018

Date of Analysis: 19/12/2018


Item No.	Lab Ref No.	SAMPLE LOCATION & DESCRIPTION	ASBESTOS FIBRE TYPE
16	BS022281	01 - CORRUGATED ROOF SHEETING TO GARAGE	Chrysotile + Amosite

**Notes:**

Method Statement: Testing was performed in accordance with the Quality Control Manual in-house method of Eton Environmental Group Ltd, based on the published method HSG248. These results only apply to the sample analysed. Eton Environmental Group Ltd cannot accept responsibility for any discrepancy or inaccuracy arising from collection, labelling or description of samples by a third party.

NAD = No Asbestos Detected In Sample


Authorised Signatory:  
Andrew Graham  
Quality Manager



This report may only be replicated in its entirety. Copies of this report are held by Eton Environmental Group Ltd.



Laboratory, Eton Environmental Group Ltd, Unit 1, Trinity Court, Faverdale, Darlington, DL3 0PH



Registered No. 5145774 Registered Office: 135 Slough Road, Datchet, SL3 9AE

Certificate of Analysis	Issue No: 7	Form 103	Issue Date: 20/02/17	Issue by: Quality Manager
-------------------------	-------------	----------	----------------------	---------------------------