



NYMNPA

25/10/2021




c1

Gable Window




b

Entrance Door




e

Existing Double Doors



c

Bedroom Window with  
Escape Sash



d

Glass screen with Door