



Additional information to support works at Old St. Stephens Church, Fylingdales - NYM/2022/0666

- 1.0 This information is to provide information on the cupola installation regarding concerns raised by the LPA in accordance with NYM/2018/0797/LB and is not intended as a publically available supporting document to the current planning application.
- 1.1 Due to access issues It has only been possible to record interventions from inside the roof, showing where the cupola has been attached to historic roof timbers. It is however hoped the following will be sufficient as it is understood concerns are centred around that specific part of the installation.
- 1.2 It is noted that the approved drawing 019, titled *Cupola—Typical Post Repair & Strengthening Sketch* and it is suggested that complete uniformity of steel angles and positioning should not be expected owing to variations in historic timbers, with a certain amount of on-site adjustment of brackets being necessary



Approved Drawing showing steel angle and photo showing typical installation



Proposed Drawing submitted with 2018/0797/LB



Current situation showing historic timbers and new steel angle

NYMNPA
19/10/2022