

Replacement Shooting Lodge -Thimbleby Shooting Ground Thimbleby Estate **Thimbleby**

Photographs of Existing Lodge - Ecology

The lodge building to be removed is constructed of timber cladding and the roof of profile metal sheeting at a low pitch. The attached photographs demonstrate that there is no requirement for a bat scoping survey at the site as the form, shape, materials and construction of the existing lodge means there is no potential for bats to access, or roost in the building.

Internally the ceiling is fully enclosed and sealed.

